

DEPARTMENT OF THE AIR FORCE
HEADQUARTERS OGDEN AIR MATERIEL AREA (AFLC)
HILL AIR FORCE BASE, UTAH 84401



REPLY TO
ATTN OF: MML

30 Sep 71

SUBJECT: 1540-1 Film Drive Motor Speed Control Failure

TO: USAF (AFINYMA, [REDACTED])

Attached is a copy of letter forwarded to [REDACTED] Information Systems regarding a deficiency in the 1540-1 Light Table. This is being forwarded for your information and dissemination to the contracting officer and other government users of this type of Light Table.

FOR THE COMMANDER



1 Atch
MMEDP Ltr, 28 Sep 71

USAF review(s) completed.

Declass review by NGA/DoD

28 SEP 1971

MEMDP/ []

1540-1 Film Drive Motor Speed Control Failure

[]
5730 Arbor Vitae Street
Los Angeles, Ca 90045

1. COMMA/MEMDP has been advised by the 480 RTGp at Langley AFB, Va that problems have been encountered with two recently received 1540-1 light tables. On tables, Serial Number 008 and 024, the film drive motor speed control does not respond in either mode of operation. The motors run at maximum speed whenever energized.

2. Since the above mentioned tables are covered by the equipment warranty, request [] representatives visit Langley AFB and provide the necessary parts and service to remedy the problem situation. Further, request that this office be advised when the above corrective action is completed.

3. TSgt Wash/DCOIC of maintenance is the individual to contact at Langley. At Hill AFB contact [] MEMDP, telephone 801-777-7392 if required.

4. Please advise also the status of the project to improve the power cable/reel canister. As you know this deficiency was identified during acceptance testing and we would appreciate comments on what [] plans to do in this regard.

Cy to: MML, MMLT

30 Sept 71

ACTION	INFO
MML	
MML O	
MML P	
MML R	
MMLT	
SUSPENSE:	